INDIRA GANDHI NATIONAL CENTRE FOR THE ARTS

Janpath, New Delhi -110 001, www.ignca.gov.in

Documentation format for Archaeological / Heritage Sites / Monuments

Serial No.: OR / KDA/ BSR- 49

	SECTION I : IDENTIFICATION		
1. Name			
Present Past Other Name (if any):	 Kartikesvara Siva Tem Old Town, Bhubaneswa 	ple, Gandhi Garabadu Precinct, ar, DistKhurda	
2. Location			
LONGITUDE 85 ⁰ 50'12" E	LATITUDE 20 ⁰ 14'27" N	ELEVATION 73 ft	
Address	: Village (village code) Post : Old Town Tehsil: Bhubaneswar State : Orissa Old Town Via: Bhubaneswar District: Khurda PIN: 751002		
Approach	: The temple is situated at the distance of 100mtrs from eastern gateway of Lingaraja temple. It is on the left side of the temple road leading from Lingaraja to Garage Chowk, within the precinct of Gandhi Garabadu.		
3. Property Type			
BuildingsPalaceFortCitadelGovt. buildingRailway stationDefence buildingIndustrial buildingOther public buildingsResidential building	Religious structures Image: Church Minar Church Monastery Stupa Tomb, Mausoleum	Other Structures Wall Gateway Pillar Others (specify)	
Engineering structure Bridge Tunnel Other engineering structure	Park or garden	Note: It has a <i>rekha vimana</i> and <i>pidha</i> <i>jagamohan</i> of <i>Kalingan</i> order.	
	Graveyard Baolis, Well Tank Cave		

4. Property Use				
		ABANDONED / IN USE : In use		
Present	:	It is a living temple and the enshrining deity is Sivalinga within a circular Yonipitha.		
Past	:	Worshipped.		
5. Age (Source)				
PERIOD YEARS Precise date of Construction Completion Subsequent changes Destruction / Demolition		Ganga rule 13 th century A.D. Second quarter of the 13 th century A.D. 		
6. Ownership / Level of Protection				
Public : Archaeological Survey ofIndia / State ArchaeologyDepartment / Any Other (Pleasespecify)PrivateAny other (Please specify)	:	SINGLE /MULTIPLE : Multiple Lingaraja Temple Administration The temple is looked after by the <i>Gandhi Garabadu</i> <i>Mahaprasad Anusthana</i> under the chief priest Gandhi		
Name Address Phone 7. Association	:	Garabadu. Old Town, Bhubaneswar, Khurda. 		
 WITH EVENTS In History In Rituals In Building Construction Any other (specify) WITH PERSONS 	:	 		
Patron Architect / Engineer Any other (specify)	:	Originally, the Gangas but now the temple is looked after by the <i>Ganddhi Garabadu Mahaprasad</i> <i>Anusthana</i> . Lingaraja Temple Administration		
8. Statement of Significance				
Architectural Archaeological Historical Religious		Architectural		
Any other (specify)	:	On the basis of architectural style the temple can be dated to the 13 th century A.D.		

SECTION II: DESCRIPTION

Context Urban / Rural Setting Surroundings	:	* Drawings (Attach extra sheet if ne	cessary) : No Urban setting
Surroundings		Stand in Isolation Integral part of a Landscape / Street / Complex :	Street
Quantification	_	4.20 mtrs x 4.20 mtrs x 6.40 mtrs	
Area Dimension (L x B x H)	:	4.20 mus x 4.20 mus x 6.40 mus	(m / cm/ feet / inch
Number of Blocks	:	Тwo	Υ.
Number of Stories	:		
Spatial Organization			
Orientation	:	The vimana is facing towards west.	
Plan	:	The sanctum is square on plan.	
Allocation of Spaces	:		
ARCHITECTURAL STYLE			
Ornamentation			
Exteriors	:	The temple is devoid of archi	
		sculptural embellishments except	angashikharas an
Interiore	_	<i>bhumiamlas</i> on the <i>gandi</i> .	
Interiors Movable Collections	:	plain	
* Any Other (specify)	 plain The temple is <i>pancharatha</i> on plan. The temple but up to <i>jangha</i> portion so its <i>bada</i> is <i>trianga</i> or <i>pancha</i> can not be retrived. The door jambs of the <i>jagamoh</i> carved with three plain vertical bands and an imag Gajaluxmi at the <i>lalatabimba</i>. The architrave above doorjambs is carved with the usual <i>navagraha</i> panel. 		trianga or panchang s of the jagamohan nds and an image c architrave above th
10. Construction Technology			
Structural System	: The <i>vimana is a rekha</i> temple and the <i>jagamohana pidha</i> temple of <i>Kalingan</i> order.		the <i>jagamohana</i> is
Building Techniques Material of Construction	:	Ashlar dry masonry. Laterite	
11. Condition Assessment			
In GeneralGood / Fair✓Sign of Deterioration✓Serious Deterioration✓Danger of Disappearance		: Fair	

In Brief (Attach extra sheet if necessary):

It is in bad state of preservation. Creepers and wild vegetations have grown mainly on the roof of the *jagamohana* and *vimana* and seepage of rain water directly into the *sanctum* because the *mastaka* is missing now. Encroachment is the greatest problem of the monument.

12. Threats to the Property

	\checkmark	Natural Negligence			
	▼ ✓	Vandalism			
	V V	Urban Pressures			
	•	Orbait Flessules			
* * * * * * * * * * * * * * * * * * * *					
SECTION III: REFERENCES					
13. Reference	Sources (published and	unpublished textual details)			
1.					
2.					
14. Photograp	ohs: 09 nos				
		(attach list as in page 6, in case of multiple photographs)			
Photo Refere	nco :				
CAPTION					
15. Audio / Vi	deo .				
		(related to rituals / performance / festivals etc.)			
Reference		, ,			
DESCRIPTIO					
DESCRIPTION	N .				
16. Maps/Plans/Drawings					
17. Listers					
NAME :	Ashis Ranjan Sahoo.	NAME :			
18. Reviewers					
NAME : COMMENTS	Dr. S. Pradhan	NAME : COMMENTS :			